

Subject: BrightDrop Electric Van Exterior Panel Dimensions

Models Years

Affected: 2023 & Beyond

Models Affected: 400 & 600

Origination Date: November 13, 2023

Revision Date: September 11, 2024


ADVISORY:

Condition/Concern:

Several Customers and Upfitters have inquired about exterior panel dimension such doors, body sides and the roll up door. The dimensions are typically used for advertising purposes such applying decals and wraps.

Additional Information:

If any more specific dimensions are needed, please contact us on www.gmupfitter.com.



The only difference between BrightDrop 400 and BrightDrop 600 is the length of the cargo side panel & roof panel. Please see pic. The rest of the dimensions (front, side, & rear) are the same as BrightDrop 600.

General Motors Upfitter Integration

http://www.gmupfitter.com

Bulletin #197b


Date: September 11, 2024

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of


conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.



ROOF




REAR



Bulletin #197b

FRONT



General Motors Upfitter Integration

http://www.gnupfitter.com

Page | 2

Date: September 11, 2024

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of

conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.